



Conversion for degrees hardness into ppm is ' $dk * 17.86 = ppm$ '

Conversion for ppm into degrees hardness is ' $ppm / 17.86 = dk$ '